

CORNER RECORD

Document Number


239

A portion of the SE 1/4 Sec. 6, T. 23N. R. 14 E., M.D.M.

County of PLUMAS

, California

Brief Legal Description PARCEL 2 OF 6 PM 49



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey JUNE 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found points as shown and described on attached sketch and as shown on 6 PM 49.

A description of the physical condition of the monument as found and as set or reset:

Found points as described and in good condition. Points set as shown on attached sketch.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 23, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-25 2003 and
examined and filed 7-8 2003.Signed R. Tom Shantz Title Plumas County Surveyor

County Surveyor's Comment _____



LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843
- (R1) RECORD per 6 PM 49 and measured.
- Searched for, not found.

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571