


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors' Act at the request of Robert Thompson in July, 1997.




John W. Hamby LS 2843

This map has been examined in accordance with Section 8766 of the Land Surveyors' Act this 15TH day of October, 1997.

R Tom Hunter
R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/00

Filed this 15TH day of October, 1997 at 2:27 .m. in
Book 11 of Record of Surveys, at page 16, at the request
of the County Surveyor.

Fee \$800
File No. 7311

Judith Wells
County Recorder
by 
Deputy

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843
- FOUND 3/4" Iron Pipe tagged LS 6051 per 9 RS 25.
- Nothing Found or Set

(R1) RECORD per 9 RS 25

(R2) RECORD per 575 OR 227

The Basis of Bearings for this map is the 1/16 line shown as N01°05'55"W on 9 RS 25, Plumas County Records.

A portion of the SW 1/4 of Section 21
T. 23 N., R. 14 E., M.D.M.

Plumas County ~ California
Scale 1" = 50' JULY, 1997

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(916) 832-5571