

SECTION 10

⑥③ NW CORNER SECTION 10

RECORD: BLM BC CAP

FD: BLM BC (12RS142)

SET: NOTHING — ACCEPTED BLM CORNER

⑥④ N 1/4 CORNER SECTION 10

RECORD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

FD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

SET: NOTHING — ACCEPTED EXISTING CORNER

⑥⑤ WITNESS CORNER TO THE N 1/4 SECTION 10

RECORD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

FD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

SET: NOTHING — ACCEPTED EXISTING CORNER

⑥⑥ NE 1/16 CORNER SECTION 10

RECORD: 5/8"REBAR W/2"ALM CAP LS 2843 (12RS142)

FD: 5/8"REBAR W/2"ALM CAP LS 2843 (12RS142)

SET: NOTHING — ACCEPTED EXISTING CORNER

⑥⑦ W 1/4 CORNER SECTION 10

RECORD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

FD: 1/2"REBAR W/PLASTIC CAP RCE 22836 (12RS142)

SET: NOTHING — ACCEPTED EXISTING CORNER

⑥⑧ CE 1/16 CORNER SECTION 10

RECORD: NONE

FOUND : NOTHING

SET: STANDARD USFS MONUMENT

FWB: 1" I.P. N21°28'16"W 108.07' (TAGGED RCE 7294)

FWB: 10" P.PINE SCRIBED"SE 1/16 S10 BT"N88°10'W 29.2' NBT

⑥⑨ CS 1/16 CORNER SECTION 10

RECORD: NONE

FD: NOTHING

SET: STANDARD USFS MONUMENT IN MOS

FWB: 6" CEDAR SCRIBED"CS 1/16 S10 BT"N20°13'E 37.3' NBT

FWB: 15" P.PINE SCRIBED "CS 1/16 S10 BT"N82°25'E 117.7' NBT

⑦⑩ SE 1/16 CORNER SECTION 10

RECORD: NONE

FD: NOTHING

SET: STANDARD USFS MONUMENT IN MOS

FWB: 1/2"REBAR W/PLASTIC CAP RCE 22836 N13°13'15"W 36.3'

FWB: 10" P.PINE SCRIBED"N 1/16 S10 BT"N88°10'W 29.2' NBT

⑦① SW CORNER SECTION 10

RECORD: USFS MONUMENT (12RS142)

FD: USFS MONUMENT (12RS142)

SET: NOTHING — ACCEPTED EXISTING USFS CORNER

⑦② S 1/4 CORNER S10

RECORD: 5/8"RB 2"ALM CAP LS 2843 (12RS142)

FD: 5/8"RB 2"ALM CAP LS 2843 (12RS142)

SET: NOTHING, ACCEPTED EXISTING CORNER (12RS142)

⑦③ E 1/16 CORNER SECTION 10/15

RECORD: 2"ID IP W/2"ALM CAP LS 3185 (12RS142)

FD: 2"ID IP W/2"ALM CAP LS 3185 (12RS142)

FWB: 2"ID IP N30°32'W 95.06' LS 2587(OLD PROP. COR.)(4RS118)

SET: NOTHING — ACCEPTED LS 3185 (12RS142)

⑦④ E 1/16 CORNER SECTIONS 3/10

RECORD: 5/8"RB 2"ALM CAP LS 2843 (12RS142)

FD: 5/8"RB 2"ALM CAP LS 2843 (12RS142)

SET: NOTHING, ACCEPTED EXISTING CORNER (12RS142)

**DETAIL FOR
REMONUMENTATION
SE 1/16 S15 T23NR11E MDM**RECORD: 2"ALUMINUM CAP
MKD. LS 2843

FOUND: NO CORNER IS OBLITERATED

RESET: OBLITERATED CORNER
WITH A STANDARD USFS
MONUMENT LS 5623

NOT TO SCALE**GENERAL NOTES**

A STANDARD UNITED STATES FOREST SERVICE (USFS) DRIVE-IN MONUMENT IS A 5/8" DIAMETER ALUMINUM ROD WITH A 3-1/4" ALUMINUM CAP EDGE-MARKED WITH THE USFS LOGO.

A STANDARD BUREAU OF LAND MANAGEMENT (BLM) MONUMENT IS A 2-1/2" DIAMETER STEEL PIPE, 28" LONG WITH A 3-1/2" BRASS CAP EDGE-MARKED WITH THE BLM LOGO.

SHEET INDEX

SECTION 11 T23NR11E MDM	1 OF 11
SECTION 6 & 7 T23NR12E MDM	2 OF 11
SECTION 2 T22NR11E MDM	3 OF 11
SECTION 12 T23NR11E MDM	4 OF 11
SECTION 27 & 26 T23NR11E MDM	5 OF 11
SECTION 10 T23NR11E MDM	6 OF 11
CORNER NOTES S11	7 OF 11
CORNER NOTES S6 S7 S12 S2	8 OF 11
CORNER NOTES S27 S26	9 OF 11
CORNER NOTES S10	10 OF 11
BLM FIELD NOTES S27, S26	11 OF 11

RECORD OF SURVEY

SECTIONS 10, T23N R11E, MDM
PLUMAS COUNTY, CALIFORNIA

FOR
U.S.D.A. PLUMAS NATIONAL FOREST
159 LAWERENCE ST
QUINCY, CA. 95971

DRAWN BY: B. SNOW

DATE: DECEMBER, 2011

SHEET 10 OF 11