

|                                                                                                  |                                                                                                                                                                                                                                           |
|--------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| T 24 N R 10 E<br>SW 1/16 S 11                                                                    | CORNER No.45<br>Set 5/8' rebar<br>capped LS 2843<br>Bearing tree tag on<br>24" Pine N53°10'E 26.2 ft.                                                                                                                                     |
| T 24 N R 10 E<br>SE 1/16 S 11                                                                    | CORNER No.46<br>Set 5/8' rebar<br>capped LS 2843<br>Bearing tree tag on<br>7" Pine S73°W 6.8ft.                                                                                                                                           |
| T 24 N R 10 E<br>Property Corner                                                                 | CORNER No.47<br>Set 5/8' rebar<br>capped LS 2843<br>Bearing tree tag on<br>15" Cedar N79°W 15.3 ft.                                                                                                                                       |
| T 24 N R 10 E<br>Property Corner                                                                 | CORNER No.48<br>Set 5/8' rebar<br>capped LS 2843<br>Bearing tree tag on<br>18" Pine S19° 10'E 19.8 ft.                                                                                                                                    |
| T 24 N R 10 E<br>Property Corner                                                                 | CORNER No.49<br>Set 5/8' rebar<br>capped LS 2843<br>Bearing tree tag on<br>12" Fir S46° 25'E 13.6 ft.                                                                                                                                     |
| T 24 N R 10 E<br>1/4 $\frac{S11}{S14}$<br>1971                                                   | CORNER No.50<br>Fd. standard BLM Mon.<br>13" Cedar N47°E 27 lks<br>Blazed scribed<br>9' BLACK OAK S40°E 25LKS<br>Blazed scribed<br>36" Pine Dead and down<br>S43°W 7 lks<br>Blazed and scribed<br>16" Pine N41°E 68 lks<br>Blazed scribed |
| T 24 N R 10 E<br>R.M.<br>20F<br>to Sec<br>1971<br>S01°07'27"E to Southeast<br>corner Section 11. | CORNER No.51<br>Fd. standard BLM Mon.<br>36" Pine S17°W 12 lks<br>Blazed scribed<br>17" Cedar N37°E 65 lks<br>Blazed scribed<br>24"Pine N36°W 25 lks<br>Dead on ground<br>8" Cedar S6°W, 88 lks.                                          |

RECORD OF SURVEY  
for  
SIERRA PACIFIC INDUSTRIES

A portion Sections 3,4,5,9,10 & 11  
T. 24 N., R. 10 E., M.D.M.  
Plumas County ~ California  
Scale 1" = 500' Jan, 2003

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571