

T22N R13E 1/4 S29 S28 1975 CORNER No. 118 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN PINE AND CEDAR. FD. AN 8" CEDAR SNAG, S48°E, 13.9' -VS REC. A 7" CEDAR, S48°E, 21 LKS (BLM 1975) FD. AN 11" PONDEROSA PINE, S86°W, 17.8' -HB REC. A 7" JEFFREY PINE, S86°W, 27 LKS (BLM 1975)	T22N R13E 1/4COR S30 S31 LS 4208 1989 CORNER No. 126 FD. A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD PER (1)2. CORNER FALLS ON TOP OF A STEEP NORTHWEST-SOUTHEAST RIDGE, 3' SOUTH OF A POWER POLE. FD. A 16" PINE STUMP, S86°E, 8.0' REC. A 15" YELLOW PINE, S66°E, 7.9' (1)2	CORNER NOTES HB = HEALED BLAZE VS = VISIBLE SCRIBING BCIP = BRASS CAPPED IRON PIPE () 1 RECORD PER 5 R/S 110 () 2 RECORD PER 9 R/S 50 () 3 RECORD PER 10 PM 86 () 4 RECORD PER 4 R/S 86 () 5 RECORD PER 4 PM 92 () 6 RECORD PER 3 PM 9 () 7 RECORD PER 2 R/S 30 () 8 RECORD PER 11 R/S 141 () 9 RECORD PER 7 R/S 26 () 10 RECORD PER 3 R/S 71 () 11 RECORD PER 8 M 33 () 12 RECORD PER 8 R/S 92 () 13 RECORD PER 11 R/S 141		T22N R13E 1/4 S33 S34 1975 CORNER No. 139 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN THICK TIMBER. FD. A 9" INCENSE CEDAR, N29°E, 31.7' -VS REC. A 6" CEDAR, N29°E, 48 LKS (BLM 1975) FD. A 23" INCENSE CEDAR SNAG, S58 1/4°E, 11.2' -VS REC. A 24" CEDAR, S58°E, 17 LKS (BLM 1975) FD. A 7" INCENSE CEDAR, S64°W, 23.8' -HB REC. A 5" CEDAR, S64°W, 36 LKS (BLM 1975)	T22N R13E 1/4 S34 S3 T21N 1975 CORNER No. 147 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE EASTERLY SLOPE IN BRUSH AND SPARSE TIMBER. FD. A 14" INCENSE CEDAR, S69°E, 38.9' -VS REC. A 13" CEDAR, S69°E, 59 LKS (BLM 1975) FD. A 35" PONDEROSA PINE, N34°E, 24.2' -VS REC. A 35" JEFFREY PINE, N33 1/4°E, 37 LKS (BLM 1975)
T22N R13E 1/4 S28 S27 1975 CORNER No. 119 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A STEEP WEST SLOPE IN A CLEARING. FD. A 16" PONDEROSA PINE, N60°W, 42.9' -VS REC. A 13" JEFFREY PINE, N60°W, 35 LKS (BLM 1975) FD. A 15" FORKED JUNIPER, S87°, 35.6' -VS REC. A 14" JUNIPER, S86°E, 54 LKS (BLM 1975)	T22N R13E 1/4 S29 S32 1975 CORNER No. 128 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN SCATTERED PINE AND JUNIPER, 40'± SOUTHWEST OF A NORTH-SOUTH SPUR. FD. A 25" PONDEROSA PINE, N1°W, 33.3' -HB REC. A 21" JEFFREY PINE, N2 1/2°W, 50 LKS (BLM 1975) FD. A 17" PONDEROSA PINE, S5°W, 48.8' -HB REC. AN 11" JEFFREY PINE, S5°W, 74 LKS (BLM 1975)			S 1/6 C S33 C LS 4753 2003 CORNER No. 140 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN PINE AND CEDAR. SCRIBED A 10" PONDEROSA PINE, S12 1/2°E, 27.8' "CS 1/16 S33 BT" SCRIBED A 13" PONDEROSA PINE, N76 1/2°W, 37.5' "CS 1/16 S33 BT"	RM T22N R13E S35 1975 CORNER No. 148 <u>34 35</u> 3 2 FD. A 38" WHITE FIR SNAG TREE CORNER WITH HEALED BLAZES ON 4 SIDES FROM WHICH THE REFERENCE MONUMENT BEARS N 30°44' E, 14.79'. CORNER FALLS ON A STEEP EAST SLOPE IN THICK TIMBER, 100'± EAST OF AN OPEN RIDGE TOP.
S 1/6 C S29 C LS 4753 2003 CORNER No. 120 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS ON A MODERATE EAST SLOPE, 75' EAST OF A ROAD IN TIMBER. SCRIBED A 10" PONDEROSA PINE, N30 1/2°E, 19.9' "CS 1/16 S29 BT" SCRIBED A 10" PONDEROSA PINE, S64 1/4°E, 23.4' "CS 1/16 S29 BT"	T22N R13E S29 S28 S32 S31 1975 CORNER No. 129 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A STEEP WESTERLY SLOPE, 10'± SOUTH OF AN OLD SKID ROAD. FD. A 30" PONDEROSA PINE, S45°W, 40.9' -HB REC. A 20" YELLOW PINE, S45°W, 63 LKS (BLM 1975) FD. A 30" PONDEROSA PINE, S73°E, 61.4' -VS REC. A 20" YELLOW PINE, S73°E, 90 LKS (BLM 1975) FD. A 26" PONDEROSA PINE, NORTH, 38.9' -VS REC. A 20" YELLOW PINE, NORTH, 59 LKS (BLM 1975)	NE 1/6 • S28 LS 4753 2003 CORNER No. 134 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTH SLOPE IN FIR AND CEDAR. SCRIBED A 12" DOUGLAS FIR, S8 1/2°W, 19.0' "NE 1/16 S33 BT" SCRIBED AN 8" INCENSE CEDAR, N50 3/4°E, 8.5' "NE 1/16 S33 BT"	SE 1/6 • S33 LS 4753 2003 CORNER No. 141 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE EAST SLOPE IN PINE, FIR AND CEDAR. SCRIBED A 0" INCENSE CEDAR, N87°E, 16.1' "SE 1/16 S33 BT" SCRIBED AN 8" INCENSE CEDAR, N45°W, 27.5' "SE 1/16 S33 BT"	N 1/6 C S4 C LS 4753 2002 CORNER No. 149 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD - NO ROCKS FOR MOUND. CORNER FALLS AT THE BASE OF A STEEP NORTHWEST SLOPE. SCRIBED A 12" PONDEROSA PINE, N82°E, 10.2' "CN 1/16 S4 BT" SCRIBED A 7" PONDEROSA PINE, N20°W, 8.8' "CN 1/16 S4 BT"	
SE 1/6 • S29 LS 4753 2003 CORNER No. 121 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN SAGE AND JUNIPER. SCRIBED AN 11" FORKED JUNIPER, N68 1/2°E, 28.8' "SE 1/16 S29 BT" SCRIBED A 20" JUNIPER, S21 1/2°E, 29.2' "SE 1/16 S29 BT"	W 1/6 • S28 S33 LS 4753 2003 CORNER No. 130 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTHEAST SLOPE, 47' SOUTH OF AN OLD SKID ROAD IN PINE AND FIR. SCRIBED A 7" DOUGLAS FIR, N80°W, 14.4' "W 1/16 S28 BT" SCRIBED AN 11" DOUGLAS FIR, S36°E, 17.8' "W 1/16 S33 BT"	N 1/6 S33 S34 LS 4753 2003 CORNER No. 135 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS ON A GENTLE EASTERLY SLOPE, 40'± WEST OF A SMALL DRAW IN FIR AND CEDAR. SCRIBED AN 8" INCENSE CEDAR, N18 1/2°W, 14.2' "N 1/16 S33 BT" SCRIBED A 9" DOUGLAS FIR, S89 3/4°E, 18.5' "N 1/16 S34 BT"	T22N R13E 1/4 S33 S4 T21N 1975 CORNER No. 143 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE, 100'± WEST OF A ROAD. FD. A 10" INCENSE CEDAR, S17°W, 7.3' -VS REC. A 7" CEDAR, S17°W, 11 LKS (BLM 1975) FD. A PINE STUMP, S40°W, 33.7' -NO MKS REC. A PINE STUMP, S39 1/2°W, 51 LKS (BLM 1975) FD. A PINE STUMP, N8°E, 34.3' -VS REC. A PINE STUMP, N8°E, 52 LKS (BLM 1975)	N 1/6 C S4 C LS 4753 2002 CORNER No. 150 SET A 1/2" REBAR IN THE CENTER OF A FOREST SERVICE DIRT ROAD. SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD FOR REFERENCE MONUMENT, S68°E, 23.3' SCRIBED A 6" INCENSE CEDAR, S46°W, 14.2' "NE 1/16 S4 BT"	
S 1/6 S29 S28 LS 4753 2003 CORNER No. 122 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SPUR, 80'± SOUTHEAST OF A ROAD. SCRIBED AN 8" CEDAR, N40 1/2°W, 42.4' "S 1/16 S29 BT" SCRIBED A 9" PONDEROSA PINE, N70°E, 30.1' "S 1/16 S29 BT"	T22N R13E 1/4 S28 S33 LS 4753 2003 CORNER No. 131 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS ON A STEEP BANK ON THE WEST SIDE OF A CREEK. SCRIBED A 6" DOUGLAS FIR, S2°E, 17.8' "T22N R13E 1/4 S33 BT" SCRIBED AN 11" DOUGLAS FIR, N6°W, 19.4' "T22N R13E 1/4 S28 BT"	T22N R13E 1/4 32 33 LS 2843 CORNER No. 136 FD. AN ALUM. CAPPED 1/2" REBAR PER 6 R/S 69. CORNER FALLS ON A STEEP WEST SLOPE, 300'± WEST OF A DIRT ROAD. NO ACCESSORIES	T22N R13E E 1/6 S33 S4 T21N LS 4753 2003 CORNER No. 144 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN PINE AND CEDAR. SCRIBED A 15" N20 1/2°W, 12.6' "E 1/16 S33 BT" SCRIBED A 16" PONDEROSA PINE, S45°E, 17.1' "E 1/16 S4 BT"		
SW 1/6 • S28 LS 4753 2003 CORNER No. 123 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE IN TIMBER, 120'± NORTH OF A ROAD. SCRIBED AN 11" PONDEROSA PINE, S67 1/2°E, 9.6' "SW 1/16 S28 BT" SCRIBED AN 11" PONDEROSA PINE, S42°W, 15.9' "SW 1/16 S28 BT"	E 1/6 • S28 S33 LS 4753 2003 CORNER No. 132 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN FIR AND CEDAR. SCRIBED A 13" DOUGLAS FIR, S73°W, 37.3' "E 1/16 S33 BT" SCRIBED A 10" DOUGLAS FIR, N71°E, 4.5' "E 1/16 S28 BT"	W 1/6 C—C S33 LS 4753 2003 CORNER No. 137 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTH SLOPE IN FIR, PINE AND CEDAR. SCRIBED A 14" DOUGLAS FIR, N7°W, 11.8' "CW 1/16 S33 BT" SCRIBED A 15" DOUGLAS FIR, N11°E, 12.2' "CW 1/16 S33 BT"	T22N R13E S33 S34 S4 S3 T21N LS 4753 2003 CORNER No. 145 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE EAST SLOPE, 40'± WEST OF A CREEK AND 70'± FROM A SKID ROAD. SCRIBED A 12" DOUGLAS FIR, N22 1/2°W, 11.0' "T22N R13E S33 BT" SCRIBED AN 11" INCENSE CEDAR, N64°E, 12.2' "T22N R13E S34 BT" SCRIBED A 7" PONDEROSA PINE, S36°E, 20.1' "T21N R13E S3 BT"		
LS 4208 CORNER No. 124 FD. A 1/2" REBAR WITH AN UNREADABLE PLASTIC CAP INSIDE A 1 1/2" PIPE IN A SMALL MOUND OF STONE PER (1)2. FD. A PONDEROSA PINE STUMP, N9 1/2°E, 59.4' REC. A 30" STUMP, N6°E, 59.4' (1)2	T22N R13E S28 S27 S33 S34 1975 CORNER No. 133 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTHWEST SLOPE IN HEAVY TIMBER. FD. A 16" INCENSE CEDAR, N7°W, 15.8' -HB REC. A 14" CEDAR, N7°W, 24 LKS (BLM 1975) FD. AN 11" DOUGLAS FIR, N53°E, 20.5' -HB REC. A 5" DOUGLAS FIR, N53°E, 31 LKS (BLM 1975) FD. A 28" INCENSE CEDAR, S55°E, 21.8' -VS REC. A 27" CEDAR, S55°E, 34 LKS (BLM 1975) FD. A 14" WHITE FIR, S12°W, 46.2' -VS REC. A 7" WHITE FIR, S12°W, 70 LKS (BLM 1975)	T22N R13E C 1/4 • S33 LS 4753 2003 CORNER No. 138 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS ON A STEEP WEST SLOPE IN FIR, PINE AND CEDAR. SCRIBED A 7" DOUGLAS FIR, S24 1/2°W, 22.1' "T22N R13E C1/4 S33 BT" SCRIBED A 14" DOUGLAS FIR, N30 1/4°W, 28.7' "T22N R13E C1/4 S33 BT"	W 1/6 • S34 S3 LS 4753 2003 CORNER No. 146 SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP WEST SLOPE AT THE WEST EDGE OF A SMALL CLEARING. SCRIBED AN 11" INCENSE CEDAR, N45 1/2°W, 14.3' "W 1/16 S34 BT" SCRIBED A 19" DOUGLAS FIR, S24°W, 7.4' "W 1/16 S3 BT"		

DEL TERRA INC.
SURVEYING
1168 INDUSTRIAL ST.
REDDING, CA 96002
PHONE (530) 241-8050

SCALE: NONE DATE: AUGUST, 2003
SHEET 10 OF 11