





- LEGEND**
- FOUND point as described
 - FOUND 5/8" Rebar & Aluminum Cap LS 2843
 - FOUND 5/8" Rebar & Plastic Cap LS 2843
 - SET 5/8" Rebar & Aluminum Cap LS 2843
 - SET 5/8" Rebar & Plastic Cap LS 2843
 - Nothing Found or Set
 - (R1) RECORD per 9 M 88, Grizzly Ranch Unit 1
 - (R2) RECORD per 6 RS 66
 - [---] DENOTES Development Setback buffer
 - [---] DENOTES a conservation easement buffer
 - DENOTES a 10' P.U.E and slope easement

GRIZZLY RANCH, UNIT 2
a Planned Development
For
Grizzly Creek Development, L.L.C.

Parcel E & Parcel I of 9 M 88
and a portion of Section 16
T. 23 N., R. 14E., M.D.M.
Plumas County ~ California
Scale 1" = 50' ~ December, 2003

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571