




LEGEND

- FOUND point as described
- FOUND 5/8" Rebar & Aluminum Cap LS 2843
- FOUND 5/8" Rebar & Plastic Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843
- SET 5/8" Rebar & Plastic Cap LS 2843
- Nothing Found or Set
- (R1) RECORD per 9 M 88, Grizzly Ranch Unit 1
- (R2) RECORD per 6 RS 66
- (R3) RECORD per 5 M 142
- [---] DENOTES a conservation easement buffer
- DENOTES a 10' P.U.E and slope easement

GRIZZLY RANCH, UNIT 3
a Planned Development
For
Grizzly Creek Development, L.L.C.

A portion of the Sections 16, 17 and 21
T. 23 N., R. 14E., M.D.M.
Plumas County ~ California
Scale 1" = 100' January, 2004

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571