


BASIS OF BEARINGS

The Basis of Bearings for this map is the South line of the Southwest Quarter of Section 27 shown as N89°40'23"E on the map filed in the office of the Recorder of Plumas County in Book 12 Record of Surveys at page 90 and Book 13 Record of Surveys at page 118.

SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Professional Land Surveyors' Act at the request of Rick Joy in March, 2008.



John L. Owen
John L. Owen LS 5620
License Exp. 9-30-08

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Professional Land Surveyors' Act this 7th day of July, 2008.




R. Tom Hunter
R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/10

RECORDER'S STATEMENT

Filed this 10th day of July, 2008 at 1:55 p.m. in Book 15 of Record of Surveys, at page 13, at the request of the County Surveyor.

Fee: \$8.00
Document No. 2008-0004781
Kathleen Williams
County Recorder
By: *Clara Davis*
Deputy

This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is Recorded as Document 2003-0014386 and Document 2005-3042 of Official Records, Plumas County Records Office.



LEGEND

- FOUND point as described
 - FOUND Rebar with Aluminum Cap LS 2843 per (R1 & R3)
 - SET 5/8" Rebar with Aluminum Cap LS 5620
 - Nothing Found or Set
- (R1) RECORD and Measured per 13 RS 118
(R2) RECORD per 12 RS 90
(R3) RECORD and measured per 10 PM 87, unless shown otherwise
(R4) RECORD and Measured per 2005-0003042
(R5) RECORD and Measured per 2003-0014386

RECORD OF SURVEY for Rick Joy

Resulting Parcel 2, Doc. 2003-14386
Resulting Parcel 2, Doc. 2005-3042
A portion of Section 27 & 34
T. 23 N., R. 13 E., M.D.M.
Plumas County ~ California
Scale 1" = 300' March, 2008

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

