

SECTION 27

(45) NW SECTION CORNER SECTION 27
RECORD: BLM ALM CAP (1983 HAMILTON)
FD: BLM BC (1983 HAMILTON)
SET: NOTHING

(46) W 1/16 SECTION 22/27
RECORD: NONE
FD: NOTHING
SET: STANDARD USFS MONUMENT IN MOS
FWB: 13" DOUGLAS FIR SCRIBED "W 1/16 S22 BT" N23°02'E 32.1'
FWB: 8" BLACK OAK SCRIBED "W1/16 S27 BT" S70°07'E, 8.8'

(47) W 1/4 SECTION 27
RECORD: NO. COUNTY RECORD (GLO SANDOW 1880)
FD: 1" IP LS 5309
SET: ACCEPTED AS BEST EVIDENCE OF CORNER

(48) CW 1/16 SECTION 27
RECORD: NONE
FD: NOTHING
SET: STANDARD USFS MONUMENT IN MOS
FWB: 18" PONDEROSA PINE SCRIBED "CW 1/16 S27 BT" N09°30'W 26.2'
FWB: 18" PONDEROSA PINE SCRIBED "CW 1/16 S27 BT" N88°44'W 47.9'

(49) E 1/4 SECTION 27
RECORD: GLO (SANDOW 1880)
FD: MOUND OF STONE
SET: STANDARD USFS MONUMENT IN MOS
FWB: 12" CEDAR SCRIBED "1/4 S27 BT" N72°12'W 28.7'
FWB: 11" DOUGLAS FIR SCRIBED "1/4 S26 BT" S89°28'E 16.4'

(50) S 1/16 SECTION 28/27
RECORD: NO RECORD FOUND
FD: 3/4" IP LS 5309
SET: ACCEPTED LS5309 REPLACED 1" IP WITH STANDARD USFS
MONUMENT IN MOS (BURIED PIPE ALONGSIDE)
FWB: 22" SUGAR PINE SCRIBED "1/4 S27 BT" N36°26'E 34.9'
FWB: 18" PONDEROSA PINE SCRIBED "1/4 S27 BT" S33°20'E 21.4'

(51) SW 1/16 SECTION 27
RECORD: NONE
FD: NOTHING
SET: NOTHING AT THE TRUE CORNER POINT (CLIFF)
FWB: SET STANDARD USFS MON. IN MOS FOR WITNESS COR. N0°00'E 5.0'
FWB: 13" DOUGLAS FIR SCRIBED "SW 1/16 S27 BT" N38°02'E 14.7'
FWB: 10" WHITE FIR SCRIBED "SW 1/16 S27 BT" N73°21'W 7.6'

(52) SW CORNER SECTION 27
RECORD: BLM BC CAP (1978)
FD: BLM BC 1978
SET: NOTHING

(53) S 1/4 SECTION 27
RECORD: NO COUNTY RECORD (GLO SANDOW 1880)
FD: 1" PIPE CAP LS3848 (ACCEPT EXISTING CORNER)
SET: NOTHING

(54) SE CORNER SECTION 27
RECORD: BLM BC CAP (1978)
FD: BLM BC (1978)
SET: NOTHING

SECTION 26

(55) N 1/4 CORNER SECTION 26
RECORD: 20" FIR (GLO SANDOW 1880)
FOUND: NOTHING

SET: STANDARD USFS MONUMENT IN MOS (SINGLE PRORATE)
FWB: 8" PONDEROSA PINE SCRIBED "1/4 S23 BT" N15°06'W 34.7'
FWB: 13" PONDEROSA PINE SCRIBED "1/4 S26 BT" S68°12'W 24.8'

(56) NE SECTION CORNER SECTION 26
RECORD: BLM BC (1978)
FOUND :BLM BC (1978)
SET: NOTHING

(57) CW 1/16 SECTION 26
RECORD: NONE
FD: NOTHING

SET: STANDARD USFS MONUMENT IN MOS
FWB: 10" PONDEROSA PINE SCRIBED "CW 1/16 S26 BT" N21°51'E 6.7'
FWB: 10" PONDEROSA PINE SCRIBED "CW 1/16 S26 BT" N50°19'W 14.4'

(58) C 1/4 SECTION 26
RECORD: NONE
FD: NOTHING

SET: STANDARD USFS MONUMENT IN MOS
FWB: 14" DOUGLAS FIR SCRIBED "C 1/4 S26 BT" N77°48'W 9.3'
FWB: 12" DOUGLAS FIR SCRIBED "C 1/4 S26 BT" S34°20'W 14.8'

(59) E 1/4 SECTION 26
RECORD: 2" ALM CAP LS 2843 (12RS41 HAMBY)
FOUND: 2" ALM CAP LS 2843 (12RS41)
SET: NOTHING

(60) W 1/16 SECTION 26/35
RECORD: NONE
FD: NOTHING
SET: STANDARD USFS MONUMENT IN MOS
FWB: 11" WHITE FIR SCRIBED "W 1/16 S35 BT" S79°48'W 11.0'
FWB: 10" WHITE FIR SCRIBED "W 1/16 S35 BT" S02°24'W 28.7'

(61) S 1/4 SECTION 26
RECORD: 1/2" REBAR AND PLASTIC CAP (4RS17)
FOUND :1/2" REBAR PLASTIC CAP (RCE 11173)(4RS17)
SET: NOTHING - ACCEPTED EXISTING CORNER

(62) SE CORNER SECTION 26
RECORD: BLM BC (1978)
FD: BLM BC (1978)
SET: NOTHING - ACCEPTED BLM CORNER

GENERAL NOTES

A STANDARD UNITED STATES FOREST SERVICE (USFS) DRIVE-IN MONUMENT IS A 5/8" DIAMETER ALUMINUM ROD WITH A 3-1/4" ALUMINUM CAP EDGE-MARKED WITH THE USFS LOGO.

A STANDARD BUREAU OF LAND MANAGEMENT (BLM) MONUMENT IS A 2-1/2" DIAMETER STEEL PIPE, 28" LONG WITH A 3-1/2" BRASS CAP EDGE-MARKED WITH THE BLM LOGO.

NOTE

ALL BLM CORNERS USED ON THIS SURVEY WERE VERIFIED AND ACCEPTED BY ME, HOWEVER, THE BLM BEARING TREES WERE NOT TIED BUT WERE CHECKED IN THE FIELD AND COMPARED WITH THE BLM FIELD NOTES.

NOTE

THE BLM CORNER NOTES FOR CORNERS (45), (52), (54), (56), (62), (37) ARE SHOWN ON PAGE 11 OF 11 OF THIS RECORD OF SURVEY.

RECORD OF SURVEY

SECTIONS 26 & 27, T23N R11E, MDM
PLUMAS COUNTY, CALIFORNIA

FOR
U.S.D.A. PLUMAS NATIONAL FOREST
159 LAWERENCE ST
QUINCY, CA. 95971

DRAWN BY: B. SNOW DATE: DECEMBER, 2011 SHEET 9 OF 11